



COMBINED NEEDLE ROLLER BEARINGS *CUSCINETTI COMBINATI A RULLINI*



811../812../ 893../894..	=	K	+	GS	+	WS
811 02 TN	=	K811 02 TN	+	GS811 02	+	WS811 02
811 03 TN	=	K811 03 TN	+	GS811 03	+	WS811 03
811 04 TN	=	K811 04 TN	+	GS811 04	+	WS811 04
811 05 TN	=	K811 05 TN	+	GS811 05	+	WS811 05
811 06 TN	=	K811 06 TN	+	GS811 06	+	WS811 06
811 07 TN	=	K811 07 TN	+	GS811 07	+	WS811 07
811 08 TN	=	K811 08 TN	+	GS811 08	+	WS811 08
811 09 TN	=	K811 09 TN	+	GS811 09	+	WS811 09
811 10 TN	=	K811 10 TN	+	GS811 10	+	WS811 10
811 11 TN	=	K811 11 TN	+	GS811 11	+	WS811 11
811 12 TN	=	K811 12 TN	+	GS811 12	+	WS811 12
811 13 TN	=	K811 13 TN	+	GS811 13	+	WS811 13
811 14 TN	=	K811 14 TN	+	GS811 14	+	WS811 14
811 15 TN	=	K811 15 TN	+	GS811 15	+	WS811 15
811 16 TN	=	K811 16 TN	+	GS811 16	+	WS811 16
811 17 TN	=	K811 17 TN	+	GS811 17	+	WS811 17
811 18 TN	=	K811 18 TN	+	GS811 18	+	WS811 18
811 20 TN	=	K811 20 TN	+	GS811 20	+	WS811 20
811 22 TN	=	K811 22 TN	+	GS811 22	+	WS811 22
811 24 TN	=	K811 24 TN	+	GS811 24	+	WS811 24
811 26 TN	=	K811 26 TN	+	GS811 26	+	WS811 26
811 28 TN	=	K811 28 TN	+	GS811 28	+	WS811 28
811 30 TN	=	K811 30 TN	+	GS811 30	+	WS811 30
811 32 TN	=	K811 32 TN	+	GS811 32	+	WS811 32
811 34 TN	=	K811 34 TN	+	GS811 34	+	WS811 34
811 36 M	=	K811 36 M	+	GS811 36	+	WS811 36
811 38 M	=	K811 38 M	+	GS811 38	+	WS811 38
811 40 M	=	K811 40 M	+	GS811 40	+	WS811 40
811 44 M	=	K811 44 M	+	GS811 44	+	WS811 44
811 48 M	=	K811 48 M	+	GS811 48	+	WS811 48
811 52 M	=	K811 52 M	+	GS811 52	+	WS811 52
811 56 M	=	K811 56 M	+	GS811 56	+	WS811 56
811 60 M	=	K811 60 M	+	GS811 60	+	WS811 60
811 64 M	=	K811 64 M	+	GS811 64	+	WS811 64
811 68 M	=	K811 68 M	+	GS811 68	+	WS811 68
811 72 M	=	K811 72 M	+	GS811 72	+	WS811 72
812 06 TN	=	K812 06 TN	+	GS812 06	+	WS812 06
812 07 TN	=	K812 07 TN	+	GS812 07	+	WS812 07
812 08 TN	=	K812 08 TN	+	GS812 08	+	WS812 08
812 09 TN	=	K812 09 TN	+	GS812 09	+	WS812 09
812 10 TN	=	K812 10 TN	+	GS812 10	+	WS812 10
812 11 TN	=	K812 11 TN	+	GS812 11	+	WS812 11
812 12 TN	=	K812 12 TN	+	GS812 12	+	WS812 12
812 13 TN	=	K812 13 TN	+	GS812 13	+	WS812 13
812 14 TN	=	K812 14 TN	+	GS812 14	+	WS812 14

811../812.	=	K	+	GS	+	WS
812 15 TN	=	K812 15 TN	+	GS812 15	+	WS812 15
812 16 TN	=	K812 16 TN	+	GS812 16	+	WS812 16
812 17 TN	=	K812 17 TN	+	GS812 17	+	WS812 17
812 18 TN	=	K812 18 TN	+	GS812 18	+	WS812 18
812 20 TN	=	K812 20 TN	+	GS812 20	+	WS812 20
812 22 TN	=	K812 22 TN	+	GS812 22	+	WS812 22
812 24 TN	=	K812 24 TN	+	GS812 24	+	WS812 24
812 26 TN	=	K812 26 TN	+	GS812 26	+	WS812 26
812 28 M	=	K812 28 M	+	GS812 28	+	WS812 28
812 30 M	=	K812 30 TN	+	GS812 30	+	WS812 30
812 32 M	=	K812 32 M	+	GS812 32	+	WS812 32
812 34 M	=	K812 34 M	+	GS812 34	+	WS812 34
812 36 M	=	K812 36 M	+	GS812 36	+	WS812 36
812 38 M	=	K812 38 M	+	GS812 38	+	WS812 38
812 40 M	=	K812 40 M	+	GS812 40	+	WS812 40
812 44 M	=	K812 44 M	+	GS812 44	+	WS812 44
812 48 M	=	K812 48 M	+	GS812 48	+	WS812 48
812 52 M	=	K812 52 M	+	GS812 52	+	WS812 52
812 56 M	=	K812 56 M	+	GS812 56	+	WS812 56
812 60 M	=	K812 60 M	+	GS812 60	+	WS812 60
812 68 M	=	K812 68 M	+	GS812 68	+	WS812 68
812 72 M	=	K812 72 M	+	GS812 72	+	WS812 72
893 06 TN	=	K893 06 TN	+	GS893 06	+	WS893 06
893 07 TN	=	K893 07 TN	+	GS893 07	+	WS893 07
893 08 TN	=	K893 08 TN	+	GS893 08	+	WS893 08
893 09 TN	=	K893 09 TN	+	GS893 09	+	WS893 09
893 10 TN	=	K893 10 TN	+	GS893 10	+	WS893 10
893 11 TN	=	K893 11 TN	+	GS893 11	+	WS893 11
893 12 TN	=	K893 12 TN	+	GS893 12	+	WS893 12
893 13 TN	=	K893 13 TN	+	GS893 13	+	WS893 13
893 14 TN	=	K893 14 TN	+	GS893 14	+	WS893 14
893 15 TN	=	K893 15 TN	+	GS893 15	+	WS893 15
893 16 TN	=	K893 16 TN	+	GS893 16	+	WS893 16
893 17 M	=	K893 17 M	+	GS893 17	+	WS893 17
893 18 M	=	K893 18 M	+	GS893 18	+	WS893 18
893 20 M	=	K893 20 M	+	GS893 20	+	WS893 20
893 22 M	=	K893 22 M	+	GS893 22	+	WS893 22
893 24 M	=	K893 24 M	+	GS893 24	+	WS893 24
893 26 M	=	K893 26 M	+	GS893 26	+	WS893 26
893 28 M	=	K893 28 M	+	GS893 28	+	WS893 28
893 30 M	=	K893 30 M	+	GS893 30	+	WS893 30
894 12 TN	=	K894 12 TN	+	GS894 12	+	WS894 12
894 13 TN	=	K894 13 TN	+	GS894 13	+	WS894 13
894 14 TN	=	K894 14 TN	+	GS894 14	+	WS894 14
894 15 M	=	K894 15 M	+	GS894 15	+	WS894 15

811../812../ 893../894..	=	K	+	GS	+	WS
894 16 M	=	K894 16 M	+	GS894 16	+	WS894 16
894 17 M	=	K894 17 M	+	GS894 17	+	WS894 17
894 18 M	=	K894 18 M	+	GS89418	+	WS894 18
894 20 M	=	K894 20 M	+	GS894 20	+	WS894 20
894 22 M	=	K894 22 M	+	GS894 22	+	WS894 22
894 24 M	=	K894 24 M	+	GS894 24	+	WS894 24
894 26 M	=	K894 26 M	+	GS894 26	+	WS894 26
894 28 M	=	K894 28 M	+	GS894 28	+	WS894 28
894 30 M	=	K894 30 M	+	GS894 30	+	WS894 30
894 32 M	=	K894 32 M	+	GS894 32	+	WS894 32
894 34 M	=	K894 34 M	+	GS894 34	+	WS894 34
894 36 M	=	K894 36 M	+	GS894 36	+	WS894 36
894 38 M	=	K894 38 M	+	GS894 38	+	WS894 38
894 40 M	=	K894 40 M	+	GS894 40	+	WS894 40
894 44 M	=	K894 44 M	+	GS894 44	+	WS894 44
894 48 M	=	K894 48 M	+	GS894 48	+	WS894 48
894 52 M	=	K894 52 M	+	GS894 52	+	WS894 52
894 56 M	=	K894 56 M	+	GS894 56	+	WS894 56
894 60 M	=	K894 60 M	+	GS894 60	+	WS894 60
894 64 M	=	K894 64 M	+	GS894 64	+	WS894 64

STO...(x)	=	RSTO...(x)	+	IR...
STO 6 (x) TN	=	RSTO 6 (x) TN	+	IR 6x10x10
STO 8 (x) TN	=	RSTO 8 (x) TN	+	IR 8x12x10
STO 10 (x)	=	RSTO 10 (x)	+	IR 10x14x12
STO 12 (x)	=	RSTO 12 (x)	+	IR 12x16x12
STO 15 (x)	=	RSTO 15 (x)	+	IR 15x20x12
STO 17 (x)	=	RSTO 17 (x)	+	IR 17x22x16
STO 20 (x)	=	RSTO 20 (x)	+	IR 20x25x16
STO 25 (x)	=	RSTO 25 (x)	+	IR 25x30x16
STO 30 (x)	=	RSTO 30 (x)	+	IR 30x38x20
STO 35 (x)	=	RSTO 35 (x)	+	IR 35x42x20
STO 40 (x)	=	RSTO 40 (x)	+	IR 40x50x20
STO 45 (x)	=	RSTO 45 (x)	+	IR 45x55x20
STO 50 (x)	=	RSTO 50 (x)	+	IR 50x60x20

NAO...	=	RNAO...	+	IR...
NAO 6x17x10 TN	=	RNAO 10x17x10TN	+	IR 6x10x10
NAO 9x22x12	=	RNAO 12x22x12	+	IR 9x12x12
NAO 12x24x13	=	RNAO 16x24x13	+	IR 12x16x13
NAO 12x24x20	=	RNAO 16x24x20	+	IR 12x16x20
NAO 12x28x12	=	RNAO 16x28x12	+	IR 12x16x12
NAO 15x28x13	=	RNAO 20x28x13	+	IR 15x20x13
NAO 15x32x12	=	RNAO 20x32x12	+	IR 15x20x12
NAO 17x30x13	=	RNAO 22x30x13	+	IR 17x22x13
NAO 17x35x16	=	RNAO 22x35x16	+	IR 17x22x16
NAO 20x35x17	=	RNAO 25x35x17	+	IR 20x25x17
NAO 20x37x16	=	RNAO 25x37x16	+	IR 20x25x16
NAO 25x40x17	=	RNAO 30x40x17	+	IR 25x30x17
NAO 25x42x16	=	RNAO 30x42x16	+	IR 25x30x16
NAO 25x42x32	=	RNAO 30x42x32	+	IR 25x30x32
NAO 30x45x13	=	RNAO 35x45x13	+	IR 30x35x13
NAO 30x45x17	=	RNAO 35x45x17	+	IR 30x35x17
NAO 30x45x26	=	RNAO 35x45x26	+	IR 30x35x26
NAO 30x47x16	=	RNAO 35x47x16	+	IR 30x35x16
NAO 30x47x18	=	RNAO 35x47x18	+	IR 30x35x18
NAO 30x52x18	=	RNAO 37x52x18	+	IR 30x37x18
NAO 35x50x17	=	RNAO 40x50x17	+	IR 35x40x17
NAO 35x55x20	=	RNAO 40x55x20	+	IR 35x40x20
NAO 35x57x20,5	=	RNAO 42x57x20	+	IR 35x42x20,5
NAO 40x55x17	=	RNAO 45x55x17	+	IR 40x45x17
NAO 40x65x20	=	RNAO 50x65x20	+	IR 40x50x20
NAO 50x68x20	=	RNAO 55x68x20	+	IR 50x55x20
NAO 50x78x20	=	RNAO 60x78x20	+	IR 50x60x20
NAO 70x100x30	=	RNAO 80x100x30	+	IR 70x80x30
NAO 75x105x25	=	RNAO 85x105x25	+	IR 75x85x25
NAO 80x110x30	=	RNAO 90x110x30	+	IR 80x90x30
NAO 90x120x30	=	RNAO 100x120x30	+	IR 90x100x30

PNA...	=	RPNA...	+	IR...
PNA 1228	=	RPNA 1528	+	IR 12x15x12
PNA 1532	=	RPNA 1832	+	IR 15x18x16
PNA 1735	=	RPNA 2035	+	IR 17x20x16
PNA 2042	=	RPNA 2542	+	IR 20x25x20
PNA 2244	=	RPNA 2844	+	IR 22x28x20
PNA 2547	=	RPNA 3047	+	IR 25x30x20
PNA 3052	=	RPNA 3552	+	IR 30x35x20
PNA 3555	=	RPNA 4055	+	IR 35x40x20
PNA 4062	=	RPNA 4562	+	IR 40x45x20

NKI...	=	NK...	+	IR...
NKI 5/12 TN	=	NK 8/12 TN	+	IR 5x8x12
NKI 5/16 TN	=	NK 8/16 TN	+	IR 5x8x16
NKI 6/12 TN	=	NK 9/12 TN	+	IR 6x9x12
NKI 6/16 TN	=	NK 9/16 TN	+	IR 6x9x16
NKI 7/12 TN	=	NK 10/12 TN	+	IR 7x10x12
NKI 7/16 TN	=	NK 10/16 TN	+	IR 7x10x16
NKI 9/12	=	NK 12/12	+	IR 9x12x12
NKI 9/16	=	NK 12/16	+	IR 9x12x16
NKI 10/16	=	NK 14/16	+	IR 10x14x16
NKI 10/20	=	NK 14/20	+	IR 10x14x20
NKI 12/16	=	NK 16/16	+	IR 12x16x16
NKI 12/20	=	NK 16/20	+	IR 12x16x20
NKI 15/16	=	NK 19/16	+	IR 15x19x16
NKI 15/20	=	NK 19/20	+	IR 15x19x20
NKI 17/16	=	NK 21/16	+	IR 17x21x16
NKI 17/20	=	NK 21/20	+	IR 17x21x20
NKI 20/16	=	NK 24/16	+	IR 20x24x16
NKI 20/20	=	NK 24/20	+	IR 20x24x20
NKI 22/16	=	NK 26/16	+	IR 22x26x16
NKI 22/20	=	NK 26/20	+	IR 22x26x20
NKI 25/20	=	NK 29/20	+	IR 25x29x20
NKI 25/30	=	NK 29/30	+	IR 25x29x30
NKI 28/20	=	NK 32/20	+	IR 28x32x20
NKI 28/30	=	NK 32/30	+	IR 28x32x30
NKI 30/20	=	NK 35/20	+	IR 30x35x20
NKI 30/30	=	NK 35/30	+	IR 30x35x30
NKI 32/20	=	NK 35/20	+	IR 30x35x20
NKI 32/30	=	NK 37/30	+	IR 32x37x30
NKI 35/20	=	NK 40/20	+	IR 35x40x20
NKI 35/30	=	NK 40/30	+	IR 35x40x30
NKI 38/20	=	NK 43/20	+	IR 38x43x20
NKI 38/30	=	NK 43/30	+	IR 38x43x30
NKI 40/20	=	NK 45/20	+	IR 40x45x20
NKI 40/30	=	NK 45/30	+	IR 40x45x30
NKI 42/20	=	NK 47/20	+	IR 42x47x20
NKI 42/30	=	NK 47/30	+	IR 42x47x30
NKI 45/25	=	NK 50/25	+	IR 45x50x25
NKI 45/35	=	NK 50/35	+	IR 45x50x35
NKI 50/25	=	NK 55/25	+	IR 50x55x25
NKI 50/35	=	NK 55/35	+	IR 50x55x35
NKI 55/25	=	NK 60/25	+	IR 55x60x25
NKI 55/35	=	NK 60/35	+	IR 55x60x35
NKI 60/25	=	NK 68/25	+	IR 60x68x25
NKI 60/35	=	NK 68/35	+	IR 60x68x35
NKI 65/25	=	NK 73/25	+	IR 65x73x25
NKI 65/35	=	NK 73/35	+	IR 65x73x35
NKI 70/25	=	NK 80/25	+	IR 70x80x25
NKI 70/35	=	NK 80/35	+	IR 70x80x35
NKI 75/25	=	NK 85/25	+	IR 75x85x25
NKI 75/35	=	NK 85/35	+	IR 75x85x35

NKI...	=	NK...	+	IR...
NKI 80/25	=	NK 90/25	+	IR 80x90x25
NKI 80/35	=	NK 90/35	+	IR 80x90x35
NKI 85/26	=	NK 95/26	+	IR 85x95x26
NKI 85/36	=	NK 95/36	+	IR 85x95x36
NKI 90/26	=	NK 100/26	+	IR 90x100x26
NKI 90/36	=	NK 100/36	+	IR 90x100x36
NKI 95/26	=	NK 105/26	+	IR 95x105x26
NKI 95/36	=	NK 105/36	+	IR 95x105x36
NKI 100/30	=	NK 110/30	+	IR 100x110x30
NKI 100/40	=	NK 110/40	+	IR 100x110x40
NKI 110/40	=	NK 120/40	+	IR 110x120x40
NKI 140/32	=	NK 155/32	+	IR 140x155x32

NKIS...	=	NKS...	+	IR...
NKIS 6 TN	=	NKS 10 TN	+	IR 6x10x13
NKIS 7 TN	=	NKS 12 TN	+	IR 7x12x16
NKIS 8	=	NKS 14	+	IR 8x14x16
NKIS 9	=	NKS 15	+	IR 9x15x16
NKIS 10	=	NKS 16	+	IR 10x16x16
NKIS 12	=	NKS 18	+	IR 12x18x16
NKIS 15	=	NKS 22	+	IR 15x22x20
NKIS 17	=	NKS 24	+	IR 17x24x20
NKIS 20	=	NKS 28	+	IR 20x28x20
NKIS 25	=	NKS 32	+	IR 25x32x22
NKIS 30	=	NKS 37	+	IR 30x37x22
NKIS 35	=	NKS 43	+	IR 35x43x22
NKIS 40	=	NKS 50	+	IR 40x50x22
NKIS 45	=	NKS 55	+	IR 45x55x22
NKIS 50	=	NKS 60	+	IR 50x60x28
NKIS 55	=	NKS 65	+	IR 55x65x28
NKIS 60	=	NKS 70	+	IR 60x70x28
NKIS 65	=	NKS 75	+	IR 65x75x28
NKIS 70	=	NKS 80	+	IR 70x80x28
NKIS 75	=	NKS 90	+	IR 75x90x32
NKIS 80	=	NKS 95	+	IR 80x95x32
NKIS 85	=	NKS 100	+	IR 85x100x32
NKIS 90	=	NKS 105	+	IR 90x105x32
NKIS 95	=	NKS 110	+	IR 95x110x32

NA...	=	RNA...	+	IR...
NA 4900	=	RNA 4900	+	IR 10x14x13
NA 4901	=	RNA 4901	+	IR 12x16x13
NA 4902	=	RNA 4902	+	IR 15x20x13
NA 4903	=	RNA 4903	+	IR 17x22x13
NA 4904	=	RNA 4904	+	IR 20x25x17
NA 49/22	=	RNA 49/22	+	IR 22x28x17
NA 4905	=	RNA 4905	+	IR 25x30x17
NA 49/28	=	RNA 49/28	+	IR 28x32x17
NA 4906	=	RNA 4906	+	IR 30x35x17
NA 49/32	=	RNA 49/32	+	IR 32x40x20
NA 4907	=	RNA 4907	+	IR 35x42x20
NA 4908	=	RNA 4908	+	IR 40x48x22
NA 4909	=	RNA 4909	+	IR 45x52x22
NA 4910	=	RNA 4910	+	IR 50x58x22
NA 4911	=	RNA 4911	+	IR 55x63x25
NA 4912	=	RNA 4912	+	IR 60x68x25
NA 4913	=	RNA 4913	+	IR 65x72x25
NA 4914	=	RNA 4914	+	IR 70x80x30
NA 4915	=	RNA 4915	+	IR 75x85x30
NA 4916	=	RNA 4916	+	IR 80x90x30
NA 4917	=	RNA 4917	+	IR 85x100x35
NA 4918	=	RNA 4918	+	IR 90x105x35
NA 4919	=	RNA 4919	+	IR 95x110x35
NA 4920	=	RNA 4920	+	IR 100x115x40
NA 4922	=	RNA 4922	+	IR 110x125x40
NA 4924	=	RNA 4924	+	IR 120x135x45
NA 4926	=	RNA 4926	+	IR 130x150x50
NA 4928	=	RNA 4928	+	IR 140x160x50
NA 6901	=	RNA 6901	+	IR 12x16x22
NA 6902	=	RNA 6902	+	IR 15x20x23
NA 6903	=	RNA 6903	+	IR 17x22x23
NA 6904	=	RNA 6904	+	IR 20x25x30
NA 69/22	=	RNA 69/22	+	IR 22x28x30
NA 6905	=	RNA 6905	+	IR 25x30x30
NA 69/28	=	RNA 69/28	+	IR 28x32x30
NA 6906	=	RNA 6906	+	IR 30x35x30
NA 69/32	=	RNA 69/32	+	IR 32x40x36
NA 6907	=	RNA 6907	+	IR 35x42x36
NA 6908	=	RNA 6908	+	IR 40x48x40
NA 6909	=	RNA 6909	+	IR 45x52x40
NA 6910	=	RNA 6910	+	IR 50x58x40
NA 6911	=	RNA 6911	+	IR 55x63x45
NA 6912	=	RNA 6912	+	IR 60x68x45
NA 6913	=	RNA 6913	+	IR 65x72x45
NA 6914	=	RNA 6914	+	IR 70x80x54
NA 6915	=	RNA 6915	+	IR 75x85x54
NA 6916	=	RNA 6916	+	IR 80x90x54
NA 6917	=	RNA 6917	+	IR 85x100x63
NA 6918	=	RNA 6918	+	IR 90x105x63
NA 6919	=	RNA 6919	+	IR 95x110x63

NA 48..	=	RNA 48..	+	IR..
NA 4822	=	RNA 4822	+	IR 110x120x30
NA 4824	=	RNA 4824	+	IR 120x130x30
NA 4826	=	RNA 4826	+	IR 130x145x35
NA 4828	=	RNA 4828	+	IR 140x155x35
NA 4830	=	RNA 4830	+	IR 150x165x40
NA 4832	=	RNA 4832	+	IR 160x175x40
NA 4834	=	RNA 4834	+	IR 170x185x45
NA 4836	=	RNA 4836	+	IR 180x195x45
NA 4838	=	RNA 4838	+	IR 190x210x50
NA 4840	=	RNA 4840	+	IR 200x220x50
NA 4844	=	RNA 4844	+	IR 220x240x50
NA 4848	=	RNA 4848	+	IR 240x265x60
NA 4852	=	RNA 4852	+	IR 260x285x60
NA 4856	=	RNA 4856	+	IR 280x305x69
NA 4860	=	RNA 4860	+	IR 300x330x80
NA 4864	=	RNA 4864	+	IR 320x350x80
NA 4868	=	RNA 4868	+	IR 340x370x80
NA 4872	=	RNA 4872	+	IR 360x390x80
NA 4876	=	RNA 4876	+	IR 380x415x100

NA...2RS (RS)	=	RNA...2RS (RS)	+	IR...
NA 4900 2RS (RS)	=	RNA 4900 2RS (RS)	+	IR 10x14x14
NA 4901 2RS (RS)	=	RNA 4901 2RS (RS)	+	IR 12x16x14
NA 4902 2RS (RS)	=	RNA 4902 2RS (RS)	+	IR 15x20x14
NA 4903 2RS (RS)	=	RNA 4903 2RS (RS)	+	IR 17x22x14
NA 4904 2RS (RS)	=	RNA 4904 2RS (RS)	+	IR 20x25x18
NA 4905 2RS (RS)	=	RNA 4905 2RS (RS)	+	IR 25x30x18
NA 4906 2RS (RS)	=	RNA 4906 2RS (RS)	+	IR 30x35x18
NA 4907 2RS (RS)	=	RNA 4907 2RS (RS)	+	IR 35x42x21
NA 4908 2RS (RS)	=	RNA 4908 2RS (RS)	+	IR 40x48x23
NA 4909 2RS (RS)	=	RNA 4909 2RS (RS)	+	IR 45x52x23
NA 4910 2RS (RS)	=	RNA 4910 2RS (RS)	+	IR 50x58x23

NA...2RS (x)	=	RNA...2RS (x)	+	IR...
NA 22/6 2RS (x)	=	RNA 22/6 2RS (x)	+	IR 6x10x12
NA 22/8 2RS (x)	=	RNA 22/8 2RS (x)	+	IR 8x12x12
NA 2200 2RS (x)	=	RNA 2200 2RS (x)	+	IR 10x14x14
NA 2201 2RS (x)	=	RNA 2201 2RS (x)	+	IR 12x16x14
NA 2202 2RS (x)	=	RNA 2202 2RS (x)	+	IR 15x20x14
NA 2203 2RS (x)	=	RNA 2203 2RS (x)	+	IR 17x22x16
NA 2204 2RS (x)	=	RNA 2204 2RS (x)	+	IR 20x25x18
NA 2205 2RS (x)	=	RNA 2205 2RS (x)	+	IR 25x30x18
NA 2206 2RS (x)	=	RNA 2206 2RS (x)	+	IR 30x35x20
NA 2207 2RS (x)	=	RNA 2207 2RS (x)	+	IR 35x42x23
NA 2208 2RS (x)	=	RNA 2208 2RS (x)	+	IR 40x48x23
NA 2209 2RS (x)	=	RNA 2209 2RS (x)	+	IR 45x52x23
NA 2210 2RS (x)	=	RNA 2210 2RS (x)	+	IR 50x58x23